



Mounting Instructions for MK II Twist Protector

In the past we often had repairs on the PRO35 Image Converter power connector caused by accidental turning of the plug inside the connector when disconnecting the power cable. The PRO35 MKII power supply cable is now equipped with a twist protector to avoid damage to the RS connector on the PRO35.



The twist protector is already installed on the power cable included in the PRO35 MKII. The PRO35 MKII is prepared with a small threaded hole next to the power connector where the twist protector fits in.

Earlier models of the PRO35 can be upgraded with the threaded hole. For upgrade of the PRO35 connector plate please contact us. The twist protector is also sold separately for an easy upgrade of existing power cables.



The twist protector can be installed or removed without any damage or rework of the power cable or the connector itself.

Delivery Content

- Twist protector (2 parts)
- 2 screws (DIN 963 M1,6x5)


You need a flat-head screwdriver (size 00) and the PRO35 power cable with angled plug.

- 1) Open the twist protector and place the angled plug inside. Make sure the pin is parallel to the plug (see picture)
- 2) Close the protector with the cover and fix it with the two screws.



Order number

22162 Twist protector for PRO35 power cable



Mounting Instructions MK II Twist Protector

PRO35[®]
CREATED BY P+S TECHNIK